

Tech Info



Tensioning unit replacement kit 533 0097 10 (55093) for tensioner arm 533 0015 10 (55025)

Model:

E34	520, 525
E36	320, 323, 325, 328
E38	728
E39	520, 523, 525, 528, 530
E46	320, 323, 325, 328, 330
E53	3.0
E60	520, 525, 530
E61	520, 525, 530
E65	730
E66	730
E83	2.5, 3.0
Z3	2.0, 2.2, 2.8, 3.0
Z4	2.2, 2.5, 3.0




Fig. 1: 533 0015 10 (55025)



Fig. 2: 533 0097 10 (55093)

LuK AS Part No.:

533 0097 10 11 28 7 838 797-KIT

OE-No.:

533 0015 10 11 28 1 427 252
11 28 1 735 899
11 28 1 748 832

The mechanical tensioner arm **533 0015 10** has been replaced by the hydraulic tensioner arm **533 0097 10**.

This replacement kit contains all the parts required for mounting the hydraulic unit as well as the pulley.
(see Fig. 3)



Fig. 3: Parts included

(55043, 55006 plus
add on material)



Note the specifications of
the vehicle manufacturer!

United States

5370 Wegman Drive • Valley City, OH 44280
Phone 800 274 5001 • Fax 330 273 3522
www.schaeffler-aftermarket.com

Canada

2871 Plymouth Drive • Oakville, ON L6H 5S5
Phone 800 261 8111 • Fax 905 829 9034
www.schaeffler-aftermarket.com